

# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-018	Smoke	8/12/2008	ADS/TM	S09QQ_003MH	Dry	Yes	1,588.75



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-018	Smoke	8/12/2008	ADS/TM	S09QQ_003MH	Dry	Yes	1,588.75

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09SS_007G1	S09SS_007MH	S09QQ_005MH	335.8219	8
S07QQ_033G1	S07QQ_033MH	S09QQ_003MH	198.3363	8
S09QQ_005G1	S09QQ_005MH	S09QQ_001MH	245.3797	8
S09QQ_001G1	S09QQ_001MH	S09SS_001MH	239.551	8
S09SS_013G1	S09SS_013MH	S09SS_007MH	256.7937	8
S09QQ_003G1	S09QQ_003MH	S09QQ_005MH	264.4521	8
S07QQ_034G1	S07QQ_034DE	S07QQ_033MH	48.41565	8

### Observations & Photos

**Obs\_ID** S1028-018-OB01

**Address** 3402 Duvall Ave

**Status** Private

**Source** Cleanout

**Location** Yard - front

**Nearest MH** S09SS\_013MH

**Comments** Smoke from cleanout in front yard. 3402 Duvall Ave.



**Picture** \S1028-018-OB01-P01.jpg

**Comments** Front of house, 3402 Duvall Ave.